

[Menu](#)

[Home](#) [Battery Replacement](#) Battery Set for ACR RLB-32 EPIRB – P/N BBR-A3-06-2449



Battery Set for ACR RLB-32 EPIRB – P/N BBR-A3-06-2449

\$99.95

Replacement battery packs (set of 4) for ACR RLB-32. Replaces Part Number: **A3-06-2449** (your battery might have a -1 or -2 at the end > these do not mean anything, all 2449s are the same)

These battery packs consist of brand new cells and wiring connector. Plug and Play replacement for your expired battery packs. Set of 4 packs for servicing 1 beacon.

If your beacon has only Three (3) packs please order this product instead: <https://beaconbatteryreplacement.com/product/acr-rlb-36-37-38-epirb-battery/>

If you have a different part number on your current battery please contact us.

Add Gasket Grease We can send you a small packet of silicon gasket grease to apply to your cleaned gasket/o-rings during installation.

☐ Please add silicon gasket grease to my order (\$1.00)

\$0.

Options Price:	\$0.00
Product Price:	\$99.95
Total:	\$99.95

1

Add to cart

SKU: BBR-A3-06-2449(35)-1
Category: **Battery Replacement**

Description

Reviews (0)

Description

Compare part number on your battery packs. Contact us with any questions.

For instructions on removing and replacing your battery packs [click here](#).

*BBR Industries LLC is not affiliated, endorsed or authorized by ACR, McMurdo, OceanSignal or any other beacon manufacturer. We are a 3rd party battery manufacturer producing battery packs that fit these beacons.